


Secondary Dryer Lint Filter Replacement



American Aldes Dryer Lint Trap Replacement Door Part No. 99 059-1

Assuming your secondary dryer filter is the same as the one shown above, the replacement part can be ordered by speaking with a representative of American Aldes Ventilation Corporation (www.aldes.com) at 941-351-3441.

At the time of the bulletin's writing, the cost for a replacement part was ~ \$35 (excluding tax and shipping). Note: The part has been redesigned and now has a different appearance.

Dryer lint filters should be kept clean, and the dryer exhaust duct should be inspected/cleaned regularly. See the corresponding OMC bulletins for more information.

More info: $\underline{\text{www.alicantehoa.com}} \rightarrow \text{Owner Services} \rightarrow \text{OMC Bulletins}$

www.vivoportal.com → Documents → Association Documents → OMC Bulletins